

WTB27-3P2441

Industrial automation components

Manufacturer	Sick
Catalog number	wtb27-3p2441
Category	Industrial automation components
Product type	Industrial automation components
Status	Active product

Technical specification

Measurement Range	100 - 1100
Product Type	Sensor

Description

The WTB27-3P2441 sensor from SICK features a measurement range from 100 to 1100. It is an ideal solution for applications requiring precise measurement within this range.