

### 591P/0070/500/0011/SP/ARM/0/0/0

Industrial automation components

|                       |                                  |
|-----------------------|----------------------------------|
| <b>Manufacturer</b>   | Parker                           |
| <b>Catalog number</b> | 591p00705000011sparm000          |
| <b>Category</b>       | Industrial automation components |
| <b>Product type</b>   | Industrial automation components |
| <b>Status</b>         | Active product                   |

### Technical specification

No technical specifications available.

### Description

591P/0070/500/0011/SP/ARM/0/0/0, DRIVE, 3 PHASE, 50/60HZ, SUPPLY: 220-500V, AUXILIARY: 115-230 V