

WE100-P3430

Industrial automation components

Manufacturer	Sick
Catalog number	we100-p3430
Category	Industrial automation components
Product type	Industrial automation components
Status	Active product

Technical specification

Weight	0.01 kgs
Product Type	Sensor
Signal Type	30
Voltage	10 - 30 V
Current	0.1 A
Component Specifications	we100
Signal Level	30 V