

## WT100L-F1141

Industrial automation components

<b>Manufacturer</b>	Sick
<b>Catalog number</b>	wt100l-f1141
<b>Category</b>	Industrial automation components
<b>Product type</b>	Industrial automation components
<b>Status</b>	Active product

### Technical specification

<b>Weight</b>	0.02 kgs
<b>Frequency</b>	2000 Hz
<b>Measurement Range</b>	0 - 400
<b>Signal Level</b>	30 V
<b>Voltage</b>	10 - 30 V
<b>Current</b>	0.1 A
<b>Component Specifications</b>	wt100l
<b>Product Type</b>	Sensor
<b>Signal Type</b>	30