

WTB2S-2F3130

Industrial automation components

Manufacturer	Sick
Catalog number	wtb2s-2f3130
Category	Industrial automation components
Product type	Industrial automation components
Status	Active product

Technical specification

Weight	0.64 kgs
Measurement Range	1 - 36
Product Type	Sensor
Signal Type	30
Voltage	10 - 30 V
Signal Level	30 V