

## WTB2S-2P3151

Industrial automation components

<b>Manufacturer</b>	Sick
<b>Catalog number</b>	wtb2s-2p3151
<b>Category</b>	Industrial automation components
<b>Product type</b>	Industrial automation components
<b>Status</b>	Active product

### Technical specification

<b>Weight</b>	0.05 kgs
<b>Frequency</b>	1000 Hz
<b>Measurement Range</b>	1 - 150
<b>Product Type</b>	Sensor
<b>Signal Type</b>	30
<b>Voltage</b>	10 - 30 V
<b>Torque</b>	640 Nm
<b>Signal Level</b>	30 V